



Figure 1. A diagram of the Ru wet ALE process. A surface layer is formed in the first etching solution through the reaction with oxidizers and co-reactants. The surface layer is selectively removed in a second solution through reactive dissolution.