



Figure 1

Operando AP-XPS analysis of Pt-Rh thin-film sensor surface under working conditions. (a) Evolution of resistivity and (b) Rh 3d and Pt 4f AP-XPS spectra taken under UHV (i) and at working conditions (ii and iii).